Division of Health Care Facilities STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION AND PLAN OF CORRECTION (X3) DATE SURVEY IDENTIFICATION NUMBER: COMPLETED A. BUILDING: 01 - MAIN BUILDING 01 TN1915 B. WING 08/25/2014 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 431 LARKIN SPRING RD MADISON HEALTHCARE AND REHABILITATIO MADISON, TN 37115 SUMMARY STATEMENT OF DEFICIENCIES (X4) ID PROVIDER'S PLAN OF CORRECTION (X5) COMPLETE PRÉFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX (EACH CORRECTIVE ACTION SHOULD BE REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG CROSS-REFERENCED TO THE APPROPRIATE DATE DEFICIENCY) N 848 1200-8-6-.08 (18) Building Standards N 848 (18) It shall be demonstrated through the submission of plans and specifications that in The negative air pressure revealed in clean laundry each nursing home a negative air pressure shall Will be corrected by 9/30/14. The Plant Operations be maintained in the soiled utility area, tollet Director or designee will perform checks on all room, janitor 's closet, dishwashing and other clean areas monthly times 3 months and correct such soiled spaces, and a positive air pressure shall be maintained in all clean areas including, immediately. These audits and corrections will be but not limited to, clean linen rooms and clean discussed in QA/PI beginning in September. utility rooms. This Rule is not met as evidenced by: Based on observation and testing, it was determined the facility failed to maintain negative air pressure in a soiled area. The finding included: Observation and testing of clean laundry on 8/25/14 at 11:27 AM, revealed the clean side of the laundry had negative air pressure. The finding was verified by the maintenance director and acknowledged by the administrator during the exit conference on 8/25/14. Division of Health Care Facilities

STATE FORM

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

5599

HICS21

TITLE

(X6) DATE